

Replacement
sheet

DAVID B. RITCHIE
THELEN REID & PRIEST LLP
EXPRESS MAIL NO. EV310851990US
TRP DOCKET NO.: IMPJ-0004




FIG. 6A
(prior art)

Best Available Copy

Replacement
Sheet

DAVID B. RITCHIE
THELEN REID & PRIEST LLP
EXPRESS MAIL NO. EV310851990US
TRP DOCKET NO.: IMPJ-0004




FIG. 68

(PRIOR ART)




FIG. 6E

phase error
in ϕ_4

(prior art)

Best Available Copy